

**SINGAPORE CIVIL DEFENCE FORCE
FIRE SAFETY BUREAU**

25A PATERSON ROAD, SINGAPORE 238511. FAX: 8386427



Our Ref: FSB 37/86
FSB 34/86

DID: 8386453
FAX: 8386436

27 July 99

Registrar, Board of Architects (BOA)
Registrar, Professional Engineers Board (PEB)
President, S'pore Institute of Architects (SIA)
President, Institution of Engineers, S'pore (IES)
President, Association of Consulting Engineers, S'pore (ACES)

Dear Sirs

ANNEX 2

SITING OF FIRE HYDRANTS

Under cl.2.1.2.2(c) of Singapore Standard CP 29: 1988 - Code of Practice for Fire Hydrant Systems and Hosereels, the location of fire hydrants should be sited at locations not less than 6m clearance from the building.

2 Please be informed that with immediate effect, the required minimum 6m clearance between building and fire hydrant can be reduced to minimum 1000mm to allow working space for hose connection.

3 Please convey the above relaxation to members of your Institution/Association/Board.

Yours faithfully

Teo Lim Teck
Teo Lim Teck
Secretary, FSB Standing Committee
for Commissioner
Singapore Civil Defence Force

cc
CEO, PWD Corp Pte Ltd
CEO, BCA
All members of FSB Standing Committee
President, REDAS/IFE/SISV
CEO, HDB
CEO, PSA
CEO, JTC
CE, LTA (Attn: Mr Mohinder Singh)
CE, PSB (Attn: Mr Lau Keong Ong)