

17 February 2023

See **Distribution List**

REMINDER ON REQUIRED SITE CONDITIONS FOR TOP/CSC INSPECTION

Objective

1 This circular reminds the industry on the required site conditions for TOP/CSC inspections.

Background

2 The required site conditions for TOP/CSC inspections were earlier communicated to the industry through a circular (reference BCA BC 15.0.3) issued on 12 Jul 2010. Notwithstanding this, we have seen an increase in the number of incomplete sites calling for TOP/CSC inspections prematurely leading to termination of these inspections. These sites would eventually require a re-inspection and add unnecessary workload for both the project teams and government agencies. Calling for a TOP/CSC inspection when not ready, also deprives another completed site from an earlier inspection.

3 As a recap, appended below are some examples of incomplete work:

- a) No safe and proper access to or within the development;
- b) Incomplete building works, in relation to:
 - (i) Safety from falling from height;
 - (ii) Treads and risers as well as safety barrier of staircases;
 - (iii) Incomplete basic finishing work which affects TOP/CSC inspection such as measurements of width of corridors and staircases, height of safety barriers, headroom and ceiling height among others;
 - (iv) Incomplete accessibility requirements such as doors, accessible washrooms, ramps and floor surfaces, handrails and signages among others.

Please refer to Annex A for details.

Reminder On Site Condition For TOP/CSC Inspections

4 On this note, we would like to draw the attention of the industry, in particular **the Developers and supervising Qualified Persons (QPs), to ensure all building works are completed before requesting for TOP/CSC inspections.** The decision when to obtain TOP/CSC is a decision that necessarily involves the whole project team, especially the Developer and QPs of the building works.¹

Duties of stakeholders under the Building Control Act 1989 ("BC Act")

5 We also wish to highlight that the declarations of completion of building works and compliance with the regulatory requirements, submitted before a TOP/CSC inspection, when the works on site are incomplete may amount to **an offence of false declaration under section 43A of the BC Act.**

6 In addition, we would also like to highlight to the supervising QPs for the supervision of building works that it is the duty of the supervising QPs, under section 9(4) of the BC Act, to take all reasonable steps and exercise due diligence in supervising and inspecting the building works to ensure that the works are carried out in accordance with the BC Act, Regulations, and the approved plans.

Administrative Actions That May Be Taken for Incomplete Site Conditions

7 We will take administrative action against the whole project team, including the Builder, where sites with incomplete works are presented for TOP/CSC inspections. This may include actions such as, written advisory, restriction of the availability of express TOP/CSC inspections and express TOP/CSC applications for the current and other projects, and the submission of detailed reports prior to TOP/CSC inspections. This is to increase accountability amongst the project stakeholders and ensure a higher level of compliance/performance for projects.

For Clarification

8 We would appreciate if you could convey the contents of this circular to members of your organisation. For clarifications, please contact us through BCA's Online Feedback Form at <https://www.bca.gov.sg/feedbackform/>

Yours Sincerely,



DEREK ANG
DIRECTOR
BUILDING CERTIFICATION & OPS PLANNING DEPARTMENT
AUDIT & INSPECTION GROUP

¹ All building works would also include installation of lightning protection system, lifts and escalators and air-conditioning and mechanical ventilation systems


Annex A:

Examples of these incomplete building works


Incomplete safety barriers



Incomplete staircases




Incomplete façades





Incomplete accessible routes




Incomplete residenital units




Incomplete common facilities e.g. roofs and tennis courts



Incomplete lightning protection system



Storage of materials affecting TOP inspection



DISTRIBUTION (via e-mail):

President
Singapore Institute of Architects (SIA)
79 Neil Road
Singapore 088904

President
Association of Consulting Engineers, Singapore (ACES)
18 Sin Ming Lane
#06-01 Midview City
Singapore 573960

President
Institution of Engineers, Singapore (IES)
70 Bukit Tinggi Road
Singapore 289758

President
Real Estate Developers Association of Singapore (REDAS)
190 Clemenceau Avenue
#07-01 Singapore Shopping Centre
Singapore 239924

President
Singapore Contractors Association Limited (SCAL)
1 Bukit Merah Lane 2
Construction House
Singapore 159760

President
Singapore Green Building Council (SGBC)
200 Braddell Road
Block H, Level 2 BCA Braddell Campus
Singapore 579700

President
Singapore Institute of Building Limited (SIBL)
9 Ah Hood Road
#02-04
Singapore 329975

President
Singapore Institute of Surveyors & Valuers (SISV)
110 Middle Road
#09-00, Chiat Hong Building
Singapore 188968

President
Association of Property & Facility Managers (APFM)
110 Middle Road
#09-00, Chiat Hong Building

Singapore 188968

President

International Facility Management Association, Singapore Chapter (IFMA)

Killiney Road Post Office

P.O. Box 2104

Singapore 912352

President

Society of Project Managers (SPM)

Macpherson Road P.O. Box 1083

Singapore 913412

Registrar

Board of Architects (BOA)

5 Maxwell Road 1st Storey

Tower Block, MND Complex

Singapore 069110

Registrar

Professional Engineers Board, Singapore (PEB)

52 Jurong Gateway Road #07-03

Singapore 608550

Director

Building and Infrastructure

Defence Science & Technology Agency (DSTA)

1 Depot Road

Defence Technology Tower A

Singapore 109679

Deputy Chief Executive Officer

Building

Housing & Development Board (HDB)

480 Lorong 6 Toa Payoh

HDB Hub

Singapore 310480

Deputy Chief Executive

Infrastructure & Development

Land Transport Authority (LTA)

1 Hampshire Road

Block 8 Level 1

Singapore 219428

Director

Land Planning Division

JTC Corporation (JTC)

8 Jurong Town Hall Road

The JTC Summit

Singapore 609434

Director of Infrastructure

School Campus Department
Ministry of Education (MOE)
1 North Buona Vista Drive
Office Tower Level 9
Singapore 138675

Chief
Healthcare Infrastructure Project
MOH Holdings Pte Ltd (MOHH)
1 Maritime Square
#11-25, Harbourfront Centre
Singapore 099253

Chief Engineer
Development Control Department
National Environment Agency (NEA)
40 Scotts Road
Environment Building
Singapore 228231

Group Director
Policy & Planning Division
National Parks Board (NPARKS)
Singapore Botanic Gardens
1 Cluny Road
Singapore 259569

Director (Building & Estates Management)
People's Association (PA) 9
King George's Avenue
Singapore 208581

Deputy Director
Centralised Service Department, Building Plan
Public Utilities Board (PUB)
40 Scotts Road
Environment Building
Singapore 228231

Senior Director
Fire Safety Department
Singapore Civil Defence Force (SCDF)
HQ Singapore Civil Defence Force
91 Ubi Avenue 4
Singapore 408827

Assistant Chief Executive
Sentosa Development Corporation (SDC)
33 Allanbrooke Road, Sentosa
Singapore 099981

Chief
Sport Infrastructure Group
Sport Singapore (SportSG)
3 Stadium Drive
Singapore 397630

Assistant Chief Executive
Policy & Planning Group
Singapore Tourism Board (STB)
1 Orchard Spring Lane
Tourism Court
Singapore 247729

Chief Executive Officer
Urban Redevelopment Authority (URA)
45 Maxwell Road
The URA Centre
Singapore 069118

All CORENET e-Info subscribers