

5 Maxwell Road #02-00 Tower Block MND Complex Singapore 069110

Telephone : 63252211 Facsimile : 63257150

Email: bca_enquiry@bca.gov.sg Web Site: http://www.bca.gov.sg

Your Ref:

Building Engineering Division (#05-00)

Fax : 63257482 Tel : 63257480

E_mail: ong_chan_leng@bca.gov.sg

Date

: 31 Jul 2002

Our Ref : BCA BC 15.0.3 Vol 11

See Distribution List

Dear Sirs

REMOVAL OF COLUMN STARTER BARS WITHOUT QUALIFIED PERSON'S APPROVAL

Recently, we have come across 2 incidents in which the builder indiscriminately cut off some column starter bars without the knowledge of the qualified person. In one case, the column starter bars were not properly aligned with the slot holes of the precast columns above. The builder simply cut and removed some of these starter bars to facilitate the erection of precast columns. In another project, there were some eccentricities in the pile foundation due to setting out errors. The builder cut off some of the column starter bars, so as to enable the erection of the columns in the positions shown on the approved plans.

As the removal of the starter bars could have adverse implications on the structural design and integrity of the building, they should not be removed or altered without the knowledge and prior approval of the qualified person. We would appreciate it if you could inform your members about the contents of this letter and advise them to ensure that construction works (especially those affecting structural safety) should be carried out with utmost care and professionalism.

Yours faithfully

ONG CHAN LENG DIRECTOR BUILDING ENGINEERING DIVISION for COMMISSIONER OF BUILDING CONTROL

BCUs

Controller Building Control Unit Jurong Town Corporation The JTC Summit 8 Jurong Town Hall Road Singapore 609434

Manager Development & Building Control Dept Land Transport Authority 251 North Bridge Road Singapore 179102 Deputy Director (Building & Infrastructure) Defence Science & Technology Agency Building & Infrastructure 1 Depot Road #12-05 Singapore 109679

Head Building Control Unit Building & Development Division Housing & Development Board HDB Hub 480 Lorong 6 Toa Payoh Singapore 310480

DISTRIBUTION LIST

President
Professional Engineers Board, Singapore
5 Maxwell Road
1st Storey MND Complex
Tower Block
Singapore 069110

President Institution of Engineers, Singapore 70 Bukit Tinggi Road Singapore 289758

President Association of Consulting Engineers, Singapore 70 Palmer Road #04-06 Palmer House Singapore 079427

President Singapore Institute of Architects 79 Neil Road Singapore 088904

President
The Singapore Contractors Association Ltd
1 Bukit Merah Lane 2
Construction House
Singapore 159760