

Our Ref : BCA BC 15.0.3 VOL 11

Building Plan and Management Group (#07-00)  
Fax : 6325 4437  
DID : 6325 8612  
E-mail : choong\_teck\_min@bca.gov.sg

18 Dec 2012

See **Distribution**

Dear Sir/Madam

### **COMMENCEMENT OF THE BUILDING CONTROL (AMENDMENT) ACT 2012**

Amendments to the Building Control Act (Chapter 29) were passed by Parliament in September 2012. We wish to inform you that the following provisions from those amendments (details are given in Annex A) have come into effect:


- the renaming of “underground building works” to “geotechnical building works”, as this type of works will now include any earthworks or other building works for constructing or stabilising a slope with a height of more than 6 metres (measured as the vertical distance between the highest level and lowest level of the slope);
- the revising of the definitions for “owner” and “plans”;
- the requirement for immediate supervision by a qualified site supervisor during the construction of earth-retaining and stabilising structures (ERSS) in small scale building works, and

2 We would appreciate it if you could convey the contents of this circular to the members of your organisation. Should you need clarifications, you may send an email to [bca\\_enquiry@bca.gov.sg](mailto:bca_enquiry@bca.gov.sg) or call the following hotlines.

<b>Hotline</b>	<b>Contact Number</b>
Building Plans	6325 7159
Structural Plans	1800 3425222

3 Thank you.

Yours faithfully,



CHOONG TECK MIN  
DEPUTY DIRECTOR  
BUILDING CONTROL POLICIES DEPARTMENT  
for COMMISSIONER OF BUILDING CONTROL

## ANNEX A

### PROVISIONS IN THE BUILDING CONTROL (AMENDMENT) ACT 2012

Section	Provision
2(1)	<ul style="list-style-type: none"><li data-bbox="416 472 1418 689">• The term “<i>underground building works</i>” is now replaced by a new term “<i>geotechnical building works</i>”. This type of works now includes any earthworks or other building works for constructing or stabilising a slope with a height of more than 6 metres (measured as the vertical distance between the highest level and lowest level of the slope).</li><li data-bbox="416 763 1418 835">• The term “<i>owner</i>” now includes any person named in the valuation list or any person registered in the land-register.</li><li data-bbox="416 909 1418 1014">• The term “<i>plans</i>”, in relation to any building works, now includes digital representations that are generated from building information modelling.</li></ul>
7(1)(c)	<p data-bbox="416 1055 1418 1234">For small-scale building works (i.e. those building works where the project value is not more than \$7.5 million), Section 7(1)(c) requires all critical structural works (like concreting, piling, pre-stressing or tightening of high-friction grip bolts) to be carried out under the immediate supervision of at least a resident technical officer.</p> <p data-bbox="416 1308 1418 1447">These critical structural works now also include the construction of earth retaining and stabilising structures (ERSS). Please refer to Annex B for details on the scope or components of ERSS works that require immediate supervision.</p>

## **ANNEX B**

### **SCOPE OF WORKS IN THE CONSTRUCTION OF EARTH RETAINING AND STABILIZING STRUCTURES THAT REQUIRE IMMEDIATE SUPERVISION BY A QUALIFIED SITE SUPERVISOR**

<b>No</b>	<b>Type of ERSS works</b>	<b>Components requiring immediate supervision</b>
1	Construction of an earth retaining wall	All installation works of the earth retaining wall, including capping beam.
2	Construction of lateral support systems	All installation works of the elements to support the excavation, including struts and walers; king posts; soil nails; ground anchors and walers; ring beams; temporary and permanent slabs, or any other type of lateral support element.
3	Excavations	All excavation works (including slope cutting) for any area where the instrumentation readings (lateral movements, support loads or settlement) have exceeded the alert level.

#### **Elaboration on immediate supervision**

In performing immediate supervision of ERSS works, the qualified site supervisor is required to ensure that the following are carried out:

(1) Ground improvement or strengthening works

Works are carried out in full compliance with the specifications shown in the approved drawings.

(2) Instrumentation and monitoring

Instrumentation readings are taken in accordance with the frequency as stated in the approved drawings.

(3) Protective measures associated with ERSS works

Protective measures are installed in accordance with the details specified in the approved drawings.

(4) Daily inspection of ERSS works

No fewer than one inspection is carried out per day to ensure the works and activities associated with the construction of the ERSS (including excavation) are being carried out in accordance with the approved plans, including the sequence of any excavation.

**DISTRIBUTION (via e-mail):**

President  
Institution of Engineers, Singapore (IES)  
70, Bukit Tinggi Road  
Singapore 289758  
[ies@iesnet.org.sg](mailto:ies@iesnet.org.sg)

President  
Association of Consulting Engineers, Singapore (ACES)  
18 Sin Ming Lane #06-01  
Midview City  
Singapore 573960  
[secretariat@aces.org.sg](mailto:secretariat@aces.org.sg)

President  
Real Estate Developers' Association of Singapore (REDAS)  
190 Clemenceau Avenue  
#07-01 Singapore Shopping Centre  
Singapore 239924  
[enquiry@redas.com](mailto:enquiry@redas.com)

President  
Singapore Contractors Association Limited (SCAL)  
Construction House  
1 Bukit Merah Lane 2  
Singapore 159760  
[enquiry@scal.com.sg](mailto:enquiry@scal.com.sg)

President  
Singapore Institute of Architects (SIA)  
79 Neil Road  
Singapore 088904  
[info@sia.org.sg](mailto:info@sia.org.sg)

President  
Society of Project Managers (SPM)  
Macpherson Road P.O. Box 1083  
Singapore 913412  
[sprojm@yahoo.com](mailto:sprojm@yahoo.com)

President  
Singapore Institute of Building Limited (SIBL)  
70 Palmer Road,  
#03-09C Palmer House  
Singapore 079427  
[josephine@sib.com.sg](mailto:josephine@sib.com.sg)

President  
Singapore Institute of Surveyors & Valuers (SISV)  
110 Middle Road #09-00  
Chiat Hong Building  
Singapore 188968  
[sisv.info@sisv.org.sg](mailto:sisv.info@sisv.org.sg)

President  
Singapore Structural Steel Society (SSSS)  
232a River Valley Road  
Singapore 238290  
[avconsul@pacific.net.sg](mailto:avconsul@pacific.net.sg)

President  
Professional Engineers Board, Singapore (PEB)  
1st Storey, Tower Block, MND Complex,  
5 Maxwell Road  
Singapore 069110  
[registrar@peb.gov.sg](mailto:registrar@peb.gov.sg)

President  
Board of Architects (BOA)  
5 Maxwell Road  
1st Storey Tower Block, MND Complex,  
Singapore 069110  
[boarch@singnet.com.sg](mailto:boarch@singnet.com.sg)

Director  
Protective Infrastructure & Estate  
Defence Science & Technology Agency  
1 Depot Road #03-01j  
Singapore 109679  
[lcheehio@dsta.gov.sg](mailto:lcheehio@dsta.gov.sg)

Deputy Director  
Project Development & Maintenance Branch  
Ministry Of Education  
1 North Buona Vista Drive  
Office Tower Level 9  
Singapore 138675  
[eng\\_wee\\_tong@moe.gov.sg](mailto:eng_wee_tong@moe.gov.sg)

Director  
Best Sourcing Department  
Public Utilities Board (PUB)  
40 Scotts Road #18-01  
Environment Building  
Singapore 228231  
[koh\\_boon\\_aik@pub.gov.sg](mailto:koh_boon_aik@pub.gov.sg)

Deputy Chief Executive  
Infrastructure & Development  
Land Transport Authority (LTA)  
1 Hampshire Road Block 8 Level  
Singapore 219428  
[chong\\_kheng\\_chua@lta.gov.sg](mailto:chong_kheng_chua@lta.gov.sg)

Deputy Chief Executive Officer (Building)  
Housing & Development Board (HDB)  
480 Lorong 6 Toa Payoh  
HDB Hub  
Singapore 310480  
[sck2@hdb.gov.sg](mailto:sck2@hdb.gov.sg)

Director  
Engineering Planning Division  
JTC Corporation (JTC)  
8 Jurong Town Hall Road  
The JTC Summit  
Singapore 609434  
[kohchwee@jtc.gov.sg](mailto:kohchwee@jtc.gov.sg)

Director  
Building  
People's Association  
9 Stadium Link  
Singapore 397750  
[foo\\_soon\\_leng@pa.gov.sg](mailto:foo_soon_leng@pa.gov.sg)

**All CORENET e-Info subscribers**