

Our ref: APPBCA-2024-08

Building Plan & Management Group Building Plan & Universal Design Department Tel : 1800 3425222 Fax : 63344031

8 April 2024

See Distribution List

Dear Sir/Madam

# CLARIFICATION ON THE PLACEMENT OF LIFT CAR CONTROL BUTTONS INSIDE THE ACCESSIBLE LIFT

#### Aim

1 This circular aims to clarify the requirement for the position of the lift car control buttons on the side panel within an accessible lift.

## **Requirements in the Code on Accessibility 2019**

- 2 Under the Clause 4.9.5.1 of the Code on Accessibility in the Built Environment 2019 ("Code"), the lift car control buttons located inside the accessible lift must have at least one panel placed to the side of the lift car.
- 3 As explained in the circular issued on 5 July 2019, this requirement for a side panel within the accessible lift car was introduced to the Code due to wheelchair users' feedback on the challenges they faced when turning their wheelchairs around to reach the lift car control buttons placed at the front of the lift car, especially when the lift is crowded.





### Placement of the side panel control buttons

- 4 We observed in recent projects that the side panel within the accessible lift was installed very close to the front corner of the lift car whereby a wheelchair user could not access the control buttons with ease.
- 5 To meet the intent of the Code, the side panel should be placed towards the centre of the lift car side wall to ensure easy access by wheelchair users. All the buttons on the side panel must be placed at a height of between 900mm and 1200mm from the finished floor level of the lift car, and at least 350mm from any internal corner of the lift car as illustrated in the diagrams provided in Annex A.

#### For clarification

6 We would appreciate if you could convey the contents of this circular to members of your organization. For clarifications, please contact us through BCA's Online Feedback Form at https://www.bca.gov.sg/feedabackform/.

Yours faithfully


TAN JWU YIH DIRECTOR BUILDING PLAN AND UNIVERSAL DESIGN DEPARTMENT

BUILDING PLAN AND MANAGEMENT GROUP for COMMISSIONER OF BUILDING CONTROL






Annex A



(a) Isometric View of Lift Car Interior



(b) Side Elevation of Lift Car Interior





# An MND Statutory Board **DISTRIBUTION (via e-mail):**

President Association of Consulting Engineers, Singapore (ACES) 18 Sin Ming Lane #06-01 Midview City Singapore 573960

President Institution of Engineers, Singapore (IES) 70 Bukit Tinggi Road Singapore 289758

President Real Estate Developers' Association of Singapore (REDAS) 190 Clemenceau Avenue #07-01 Singapore Shopping Centre Singapore 239924

President Singapore Contractors Association Limited (SCAL) Construction House 1 Bukit Merah Lane 2 Singapore 159760

President Singapore Institute of Architects (SIA) 79 Neil Road Singapore 088904

President Singapore Institute of Building Limited (SIBL) 9, Ah Hood Road, #02-04, Singapore 329975

President Singapore Institute of Surveyors & Valuers (SISV) 110 Middle Road #09-00 Chiat Hong Building Singapore 188968

President Society of Project Management (SPM) 168 Jalan Bukit Merah Connection One #10-01 Singapore 150168 c/o SIPM Consultants Pte Ltd





President Board of Architects (BOA) 5 Maxwell Road 1st storey Tower Block MND Complex Singapore 069110

President Professional Engineers Board, Singapore (PEB) 52 Jurong Gateway Road #07-03 Singapore 608550

President Singapore Lift & Escalator Contractors & Manufacturers Association (SLECMA) 3 Raffles Place #06-01 Bharat Building Singapore 048617

President Singapore Hotel Association 17 Cantonment Road Singapore 089740

Chairman The Association of Shopping Centres (Singapore) 91 Tanglin Road #03-01 Tanglin Place Singapore 247918

President Singapore Structural Steel Society (SSSS) 1 Liang Seah Street #02-11/12 Liang Seah Place Singapore 189022

Director of Infrastructure School Campus Department Ministry of Education 1 North Buona Vista Drive Singapore 138675

Deputy Director Project Development & Management 3 Building Quality Group Housing & Development Board HDB Hub 480 Lorong 6 Toa Payoh Singapore 310480





Deputy Chief Executive Infrastructure & Development Land Transport Authority (LTA) 1 Hamphire Road Block 8 Level Singapore 219428

Director Technical Services Division JTC Corporation (JTC) 8 Jurong Town Hall Road The JTC Summit Singapore 609434

Senior Director (Building & Estates Management) People's Association (PA) 9 King George's Avenue Singapore 208581

Director Special Projects & Procurement Department PUB, Singapore National Agency 40 Scotts Road #08-01 Environment Building Singapore 228231

Chief (Sports Facilities) Sport Singapore 3 Stadium Drive Singapore 397630

Chief Executive Officer Urban Redevelopment Authority (URA) 45 Maxwell Road, The URA Centre Singapore 069118

Director Building and Infrastructure Defence Science & Technology Agency 1 Depot Road Defence Technology Tower A Singapore 109679

Head (Fire Safety and Building Control) Building and Infrastructure Defence Science & Technology Agency 71 Science Park Drive Singapore 118253





An MND Statutory Board Manager (Architectural Plans) Building and Infrastructure Defence Science & Technology Agency 71 Science Park Drive Singapore 118253

Deputy Chief Executive Officer Sentosa Development Corporation 33 Allenbrooke Road, Sentosa Singapore 099981

Chief Health Infrastructure Project MOH Holdings Pte Ltd 1 Maritime Square #11-25 HarbourFront Centre Singapore 099253

Specialists Trade Alliance of Singapore (STAS) 24 Peck Seah Street, #07-11 Nehsons Building Singapore 079314w

Singapore International Facility Management Association (SIFMA) 200 Braddell Road, #01-03 Block H, BCA Braddell Campus Singapore 579700

Association of Property and Facility Managers (APFM) 110 Middle Road #09-00 Chiat Hong Building Singapore 188968

President Singapore Green Building Council (SGBC) 200 Braddell Road Block H, Level 2 BCA Braddell Campus Singapore 579700

#### All CORENET e-Info Subscribers

